



(related art)

Figure 1






(related art)

Figure 2A




(related art)

Figure 2B




(related art)

Figure 2C



(related art)
Figure 3A



(related art)
Figure 3B

09740967 466100




Figure 4A




Figure 4B

09740967 122100




Figure 5




Figure 6

6/11




Figure 7A






Figure 7B

0072337 2350460

09740967 122100

Under Rubbing





Upper Rubbing



Figure 8A

8/11



(related art)
Figure 8B

9/11




Figure 9A




Figure 9B

10/11




Figure 10




Figure 11

US 2004/013400

